

**COBALT METAL****Application:**

- Preparation of magnetic, wear-resistant and high-strength alloys. As a radioactive tracer and to produce high energy gamma rays.

Packing: 250KG Drum**CAS No: 7440-48-4****Specifications:**

Ni	Cu	Fe(1)	Pb(=)	Mn(<1)	Si	Zn(Unit:ppm)	S	C	Co
80	6	6	<1	<1	1	<1	<1	20	99.9%
80	6	6	1	<1	<1	<1	<1	10	99.9%
80	4	7	1	<1	<1	<1	<1	10	99.9%
80	5	5	<1	<1	<1	<1	<1	10	99.9%
80	5	4	<1	<1	<1	<1	<1	10	99.9%
80	4	6	<1	<1	<1	<1	<1	10	99.9%
80	5	7	1	<1	<1	<1	<1	10	99.9%
80	4	6	2	<1	<1	<1	<1	20	99.9%